

MONUMENT RECORD  
State of Indiana - County of Monroe

Section: 32

Township: 7 North


Range: 1 East

Corner ID: Polk G-25

**Monument Description & Remarks:** 3" Aluminum disk with cap "1994 SO545". Survey Sign 3.5ft above ground at pt. B.

**References On File:** Ed Fleener, LAND CORNER RECORD A-7 (1995), on file in Surveyor Office


RECOVERY TIE DRAWING  
Field Book 38 Page No. 76



- A - 3" Aluminum disk
- B - North 0.3' to Survey Sign on metal fence post
- C - S 87° E 137.88' to 3" Aluminum disk Lawrence County Offset Corner
- D - S 39° W 16.18' to NW corner of modular home foundation
- E - N 73° W 29.30' to MAG nail in 10" power line pole

I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of section 36-2-1 of the Indiana Code; and the above data is given under my hand and seal this 26th day of January, 2007.

*Kevin P. Enright*



Administered by the Monroe County Surveyor Review Board

Date: 8-14-2007

Date: 12/12/94




Index No. Z 7  
(Alphabetical - Numerical)LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

R9-7100-74 (Rev. 5/80)

T. 7 N R. 1 E 2nd P Mer. N.F. Hoosier County Monroe State Indiana  
S. 1/4 Corner common to sections 32 and \_\_\_\_\_

## EXISTING SURVEYS

| Original Government Survey       |                                                                                   | Original Evidence Found                         |                                   |
|----------------------------------|-----------------------------------------------------------------------------------|-------------------------------------------------|-----------------------------------|
| Year surveyed                    | <u>1811 - Alex Holmes D.S.</u>                                                    | Year of search                                  | <u>1988</u> By <u>R. Ratcliff</u> |
| Original monument                | <u>Post</u><br><small>(Wood post, stone, pile of stones, pipe, etc.)</small>      | Monument found                                  | <u>None</u> <u>R.L.S.#S0343</u>   |
| Bearing Trees                    |                                                                                   | Original Bearing Trees Found                    |                                   |
| Species                          | <u>Hickory</u> <u>W.Oak</u>                                                       | Species                                         | _____                             |
| Diameter                         | <u>10"</u> <u>24"</u>                                                             | Diameter                                        | _____                             |
| Bearing                          | <u>N84E</u> <u>N65W</u>                                                           | Bearing                                         | <u>None</u>                       |
| Distance                         | <u>32 1k</u> <u>34 1k</u>                                                         | Distance                                        | _____                             |
| Subsequent Corner Restoration    |                                                                                   | Evidence of Subsequent Corner Restoration Found |                                   |
| Year surveyed                    | <u>1860</u> By <u>J.S. Buskirk MCS</u>                                            | Year of search                                  | <u>1988</u> By <u>R. Ratcliff</u> |
| Where filed or recorded          | <u>Monroe Co. Surveyor</u>                                                        |                                                 | <u>R.L.S.#S0343</u>               |
| Monument                         | <u>Not called for</u><br><small>(Original, concrete post, iron rod, etc.)</small> |                                                 | <u>None</u>                       |
| Bearing Trees, Reference Objects |                                                                                   | Bearing Trees, Reference Objects                |                                   |
| Species                          | <u>Walnut</u> <u>Sycamore</u>                                                     |                                                 | _____                             |
| Diameter                         | <u>20"</u> <u>18"</u>                                                             |                                                 | _____                             |
| Bearing                          | <u>N47W</u> <u>N82E</u>                                                           |                                                 | <u>None</u>                       |
| Distance                         | <u>259 1k</u> <u>122 1k</u>                                                       |                                                 | _____                             |



Sketch

○ Corner ■ F.S. Land

## Relation of Evidence to Record Features Along Section Lines

| Section line to sections | Township Line     |                   |
|--------------------------|-------------------|-------------------|
| Object                   | <u>Brook East</u> | <u>Brook West</u> |
| Record distance          | <u>5.00 CH</u>    | <u>3.00 CH</u>    |
| Measured distance        | <u>250'</u>       | <u>145'</u>       |

## Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

Fence running East - Old road bed North and fence running North to stone at 1/16 corner

## Perpetuation Record

Monument and accessories established. Include brief description of area.

None

At time of search:

1. Did you have the record description?

Yes X No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps, etc. Maps & Traverse3. Man hours spent in search 44. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No X5. Signature R. Ratcliff

Certified corner restoration certificate prepared:

Yes \_\_\_\_\_ No X

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. 2-7  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)  
GPO 806-924

T. 7N R. 1E 9th Mer. N.F. Hoosier County Monroe State Indiana  
5 1/4 Section Corner common to sections 32 and         

EXISTING SURVEYS

| Original Government Survey                                                                                                                                                                                                           |  | Original Evidence Found                                                                                                                                                                   |    |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----|
| Year surveyed                                                                                                                                                                                                                        |  | Year of search                                                                                                                                                                            | By |
| Original monument<br><small>(wood post, stone, pile of stones, pipe, etc.)</small>                                                                                                                                                   |  | Monument found                                                                                                                                                                            |    |
| <p>Bearing Trees</p> <p>Species <u>Hickory</u> <u>W. Oak</u></p> <p>Diameter <u>10"</u> <u>24"</u></p> <p>Bearing <u>N 84° E</u> <u>N 65° W</u></p> <p>Distance <u>32 1/2</u> <u>34 1/2</u></p>                                      |  | <p>Original Bearing Trees Found</p> <p>Species</p> <p>Diameter</p> <p>Bearing</p> <p>Distance</p>                                                                                         |    |
| <p>Subsequent Corner Restoration</p> <p>Year surveyed <u>1960</u> By <u>Buskirk</u></p> <p>Where filed or recorded <u>Monroe Co. Surv. Rec. 289</u></p> <p>Monument<br/><small>(Original, concrete post, iron rod, etc.)</small></p> |  | <p>Evidence of Subsequent Corner Restoration Found</p> <p>Year of search <u>1972</u> By <u>H Deaton</u></p> <p>Found <u>line stone 10" above ground</u><br/><u>6" x 3" Not marked</u></p> |    |
| <p>Bearing Trees, Reference Objects</p> <p>Species <u>P. Oak</u> <u>Syc</u></p> <p>Diameter <u>10"</u> <u>14"</u></p> <p>Bearing <u>N 47° W</u> <u>N 82° E</u></p> <p>Distance <u>259 1/2</u> <u>122 1/2</u></p>                     |  | <p>Bearing Trees, Reference Objects</p> <p><u>None</u></p>                                                                                                                                |    |



Sketch

○ Corner    ■ F.S. Land

Relation of Evidence to Record Features Along Section Lines

| Section line to sections | <u>5-32</u>          | <u>5-32</u>            | <u>5-32</u>     |
|--------------------------|----------------------|------------------------|-----------------|
| Object                   | <u>Break 5 1/2 S</u> | <u>Break 25 1/2 SW</u> | <u>N 1/4 55</u> |
| Record distance          | <u>W 3 chs</u>       | <u>E 5 chs</u>         | <u>E 2.54</u>   |
| Measured distance        | <u>2.16 chs</u>      | <u>3.5 chs</u>         |                 |

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

Stone is on west edge of county gravel road Mr. Lovasta Deaton who lives in NW 1/4 SE 1/4 Sec. 32 told of the location of 1/4 corner  
Fence runs east from east side of road  
Measured from stone to creek and proved stone to be in incorrect location. Were unable to locate an established corner stone.

Perpetuation Record

Monument and accessories established. Include brief description of area.

At time of search:

1. Did you have the record description?  
Yes ☒ No ☐

2. How was search area located?  
Pacing, chaining, photos, maps, etc. Photos, maps  
Pacing from stone

3. Man hours spent in search

4. Do you think additional search might recover evidence? Yes ☐ No ☒

5. Signature H Deaton

Certified corner restoration certificate prepared: Yes ☐ No ☐

Filed in county records at Date County Document No.

Identified on aerial photo No. Which is filed at